# Wisconsin Complaint Report 6/1/01 to 5/31/02

Service	Comp	laintsCA
Hung	Up on	Caller

Customer called to complain that CA 6771 disconnected him and he wanted to make another call. Customer did not leave name and number for follow-up.

Inquire Date 8/1/01
Record ID 7705
Call Taken By 6771
Responded By TB

Customer Service Manager processed the feedback form and gave it to the supervisor. Supervisor discussed the importance of processing all calls correctly. CA agreed. CA believes that the call may have been disconnected due to technical reasons. Supervisor reminded the CA to properly document this information.

**Response Date** 8/6/01 **Resolution** 8/6/01

Service Complaints--CA Hung Up on Caller

VCO customer complained that CA 6848 disconnected her call.

 Inquire Date
 5/23/02

 Record ID
 10062

A Customer Service Representative processed the feedback form and gave it to the supervisor. Supervisor validated that the CA did disconnect the call.

Call Taken By<br/>CA NumberGB/TB<br/>6848Responded ByTBResponse Date5/23/02Resolution5/23/02

WTRS never allows a CA to disconnect a customer without a supervisor's approval.

Serious disciplinary action has been taken against this CA. The supervisor was monitoring this call at the time the call was disconnected. The CA was immediately reprimanded.

## Service Complaints--CA Hung Up on Caller

Customer complained that CA 6681 disconnected her during a relay call.

 Inquire Date
 11/6/01

 Record ID
 8540

 Call Taken By
 BW/TB

 CA Number
 6681

Customer Service Manager processed the feedback form and gave it to the supervisor. The supervisor determined that the CA did disconnect the customer.

CA Number 6681
Responded By TB
Response Date 11/14/01
Resolution 11/14/01

The CA was unable to provide a reason for the incident. The CA has been coached and disciplined regarding this situation.

# Service Complaints--CA Hung Up on Caller

Customer requested CA 6830 to place a TTY to VCO call. Customer reported that the CA disconnected him.

 Inquire Date
 4/24/02

 Record ID
 9844

It was determined that the CA did disconnect the caller.

Call Taken By DT/DF CA Number 6830 Responded By TB

CSA processed the feedback form and gave it to the supervisor. Supervisor discovered that the CA did not know how to use the "orig and term select" functions correctly.

The CA has been retrained on all call issues.

 Response Date
 4/24/02

 Resolution
 4/24/02

## Service Complaints--CA Hung Up on Caller

TTY customer called to complain that CA 6585 disconnected the person he was calling. Customer requested a call back after determining what happened.

11/12/01 Inquire Date Record ID 8583 Call Taken By

CA Number 6585 Responded By TB

Customer Service Manager processed the feedback form and gave it to the supervisor.

Response Date 11/19/01 Resolution 11/19/01

CSM made several attempts to reach this customer, which included sending a letter, to gather more information. Customer did not respond.

# Service Complaints--CA Hung Up on Caller

Customer complained that CA 6713 disconnected her from the relay. After first call was completed, CA sent (ANS MACH LV MSG Q). Caller was looking for information to call back to the same number again and to leave a message on a voice answering machine.

**Inquire Date** 8/21/01 Record ID 7885 Call Taken By DF/TB CA Number 6713 Responded By TB

Customer Service Manager processed the feedback form and gave it to the supervisor. Supervisor discussed the importance of either waiting for the caller to hang up or waiting for a Supervisor to approve the use of the call disconnect procedure.

Response Date 8/23/01 Resolution 8/23/01

Second call back was made to the same number at no charge as is our policy.

# Service Complaints--CA **Typing**

TTY customer counted 21 "XXX"s on one call. Customer did not want a follow-up.

**Inquire Date** 5/23/02 Record ID 10073

CSR processed the feedback form and gave it to the supervisor. CA stated that the voice person spoke very quickly and was hard to understand.

Call Taken By JB/TB CA Number 6875

The CA unsuccessfully tried to slow the voice person down five times.

Responded By JB Response Date 5/23/02 Resolution 5/23/02 The supervisor reminded the CA of the proper procedure to give status to the TTY user when this occurs.

Supervisor will monitor the CA until further notice.

## Service Complaints--Didn't Follow Voice Mail/Recording Procedure

Inquire Date 6/19/01

Record ID 7367 Call Taken By TB

CA Number 6581 Responded By TB Response Date 6/20/01 Resolution 6/20/01

TTY customer noticed that CA 6581 did not type the complete answering machine message and did not use the recording feature during the call. CA tried to type the message manually.

Customer said a follow-up is not necessary.

Customer Service Manager processed the feedback form and gave it to the supervisor. CA did not understand that the recording feature should be used with answering machines too.

Supervisor coached the CA on the proper procedure.

Service Compla Follow Voice N Procedure		Voice customer received a message on his voice answering machine. CA left a message with a phone number but missed the last four numbers. The CA did not redial to finish recording the remaining numbers.
Inquire Date	2/26/02	
Record ID	9441	
		Customer Service Representative processed the feedback form and gave it to the supervisor.
Call Taken By	JB/TB	The CA understood that if a message is not left in its entirety on a voice answering machine,
CA Number	6748	CA is to redial and leave the remaining message.
Responded By Response Date	TB 2/27/02	
Resolution	2/27/02	The supervisor coached the CA on this procedure to ensure that it is used properly in the future.
Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquire Date	9/3/01	
Record ID	8018	
Call Taken By	VLS/TB	Supervisor informed customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
CA Number		
Responded By	VLS	
Pagnanga Data	0/2/04	On 9/3/01 – WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must
Response Date Resolution	9/3/01	be answered within ten seconds. (99 percent of all calls were answered within ten seconds.)
Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquire Date	6/25/01	
Record ID	7397	
Call Taken By	DT/TB	Supervisor informed customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
CA Number		
Responded By	DT	6/25/01 – WTRS was in compliance with the FCC rule that states 85 percent of relay calls must be answered within ten seconds. (93% of all calls were answered within ten seconds.)
Response Date		
Resolution	6/25/01	
Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquire Date	6/25/01	
Record ID	7396	
11000.00 120	. 200	Supervisor informed customer that we were experiencing high call volumes at that time and suggested that
Call Taken By	DT/TB	the customer stay on the line for the next available CA.
CA Number		
Responded By	DT	6/25/01 – WTRS was in compliance with the FCC rule that states 85 percent of relay calls must be answered within ten seconds. (93% of all calls were answered within ten seconds.)
Response Date		
D 1	CIDEID1	

Resolution

6/25/01

Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
La marin a Danta	0/00/04	
Inquire Date	6/23/01	
Record ID	7395	Supervisor informed customer that we were experiencing high call volumes at that time and suggested that
Call Taken By	DT/TB	the customer stay on the line for the next available CA.
CA Number	סוווט	the distriner stay of the fine for the flext available on.
Responded By	DT	On 6/23/01, WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (98 percent of calls was answered within ten seconds.)
Response Date	6/23/01	be answered within ten seconds. (96 percent of calls was answered within ten seconds.)
Resolution	6/23/01	
Resolution	0/23/01	
Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquina Data	7/17/01	
Inquire Date	7/17/01	
Record ID	7583	Supervisor informed customer that we were experiencing high call volumes at that time and suggested that
Call Taken By	RJ/TB	the customer stay on the line for the next available CA.
CA Number		
	DI	7/17/01 WTDS was in compliance with the ECC rule that states 95 percent of all relay calls must
Responded By	RJ	7/17/01 – WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (98 percent of calls were answered within ten seconds.)
Response Date	7/17/01	30 another and mann (an ecosition (ac person) of same more another and mann terrors.
Resolution	7/17/01	
Service Compla Ringing/No An		Customer informed us via e-mail that she called relay and experienced ringing and no answer.
•		Customer informed us via e-mail that she called relay and experienced ringing and no answer.
•		Customer informed us via e-mail that she called relay and experienced ringing and no answer.
Ringing/No An	swer	
Ringing/No An  Inquire Date Record ID	6/8/01 7298	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with
Ringing/No An  Inquire Date Record ID  Call Taken By	<i>6/8/</i> 01	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds.
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number	6/8/01 7298 PB/TB	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)
Ringing/No An  Inquire Date Record ID  Call Taken By	6/8/01 7298 PB/TB	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds.  (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By	6/8/01 7298 PB/TB	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By  Response Date	6/8/01 7298 PB/TB PB 6/8/01	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds.  (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By	6/8/01 7298 PB/TB	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds.  (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By  Response Date	6/8/01 7298 PB/TB PB 6/8/01 6/8/01	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds.  (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An	6/8/01 7298 PB/TB PB 6/8/01 6/8/01	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An	6/8/01 7298 PB/TB PB 6/8/01 6/8/01 ints- swer	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An	6/8/01 7298 PB/TB PB 6/8/01 6/8/01	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.  VCO customer informed us via fax that she called relay and experienced ringing and no answer on 2/17/02.
Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An  Inquire Date Record ID	6/8/01 7298 PB/TB PB 6/8/01 6/8/01 ints- swer 2/19/02 9416	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.  VCO customer informed us via fax that she called relay and experienced ringing and no answer on 2/17/02.  Supervisor informed customer that we were experiencing high call volumes at that time and suggested that
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An  Inquire Date Record ID  Call Taken By	6/8/01 7298 PB/TB PB 6/8/01 6/8/01 ints- swer	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.  VCO customer informed us via fax that she called relay and experienced ringing and no answer on 2/17/02.
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An  Inquire Date Record ID  Call Taken By CA Number	6/8/01 7298 PB/TB PB 6/8/01 6/8/01 ints- swer 2/19/02 9416 Supervisor/TB	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.  VCO customer informed us via fax that she called relay and experienced ringing and no answer on 2/17/02.  Supervisor informed customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
Ringing/No An  Inquire Date Record ID  Call Taken By CA Number Responded By Response Date Resolution  Service Complan Ringing/No An  Inquire Date Record ID  Call Taken By	6/8/01 7298 PB/TB PB 6/8/01 6/8/01 ints- swer 2/19/02 9416	Hamilton Contract Manager investigated and determined that on 6/7/01 WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (97 percent of calls were answered within ten seconds.)  Hamilton Contract Manager followed up with the customer and explained that WTRS was experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.  VCO customer informed us via fax that she called relay and experienced ringing and no answer on 2/17/02.  Supervisor informed customer that we were experiencing high call volumes at that time and suggested that

Response Date 2/19/02

Resolution

2/19/02

Service Compla Ringing/No An		FASTRAN trialist called to complain that she called FASTRAN and received no response or overflow to regular relay. Customer did not leave number for follow-up.
Inquire Date Record ID	3/13/02 9582	
Call Taken By CA Number	DT/TB	Supervisor informed customer that we were experiencing high call volumes at that time. Supervisor apologized to the customer for the inconvenience and suggested to continue to call FASTRAN.
Responded By	DT	Customer Service Manager investigated and found WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within 10 seconds.
Response Date	3/13/02	(99% of calls were answered within 10 seconds on 3/13/02.)
Resolution	3/13/02	
Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquire Date Record ID	3/28/02 9682	
Call Taken By CA Number	JB	Customer Service Representative e-mailed the customer and asked which number he dialed (7-1-1 or 800 number). CSR has received no response from the customer.
Responded By	JB	WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within 10 seconds. (99 percent of calls were answered within ten seconds on 3/28/02.)
Response Date	3/28/02	
Resolution	3/28/02	
Service Compla Ringing/No An		TTY customer experienced ringing and no answer.
Inquire Date Record ID	4/9/02 9742	
Call Taken By	ES	Customer Service Representative informed the customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
CA Number		
Responded By	ES	WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (98 percent of relay calls were answered within 10 seconds on 4/9/02.)
Response Date Resolution	4/9/02 4/9/02	
Service Compla Ringing/No An		Customer called 711 relay access number and experienced ringing and no answer.
Inquire Date Record ID	4/30/02 9909	
Call Taken By CA Number	RJ/TT	Supervisor Aide informed the customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.

Responded By RJ

Resolution

Response Date 4/30/02

4/30/02

WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (96 percent of relay calls were answered within ten seconds on 4/30/02.)

Service Compla Ringing/No An		Customer called relay and experienced ringing and no answer.
Inquire Date Record ID	5/6/02 9956	
Call Taken By CA Number	тт	CSR informed the customer that we were experiencing high call volumes at that time and suggested that the customer stay on the line for the next available CA.
Responded By	TT	WTRS was in compliance with the FCC rule that states 85 percent of all relay calls must be answered within ten seconds. (91 percent of calls were answered within ten seconds on 5/6/02.)
Response Date Resolution	5/6/02 5/6/02	
Technical Comp Busy Signal/Bl		Customer called in to complain that she was not able to connect to an 800 number through the relay. Customer said she has called the number successfully in the past but it did not work this time.
Inquire Date 3		
Record ID  Call Taken By	9573 JB	A customer service representative informed the technician. The CSR called the customer back and requested that the customer call back in to the relay and try again. If it still does not work, then request a supervisor.
CA Number Responded By Response Date	JB	The supervisor and CSR monitored the call and found that the 800 number was actually blocked. Supervisor was able to reach the desired number and the call then went through as to be expected.
Resolution	3/13/02	
Technical Comp Carrier Choice not Available/0		A TTY customer called because TDS Telecom is not available as a carrier of choice through the relay.
Inquire Date Record ID	4/16/02 9810	
Accord ID	5510	Supervisor explained that TDS is not a participating carrier through the relay. Hamilton has contacted this carrier and is still working with this carrier so that they will become a carrier of choice through relay.
Call Taken By CA Number	BW/TB	
Responded By B		
Response Date		
Resolution	4/16/02	

# Technical Complaints-Line Disconnected

TTY customer reached a Voice Response Unit, the CA collected the information and was then disconnected. Customer would like a follow-up as soon as possible.

Inquire Date	4/2/02	
Record ID	9696	
		Customer Service Manager processed the feedback form and gave it to the supervisor.
Call Taken By	TB	CA experienced technical difficulties. The CA called for the supervisor and had to disconnect the call.
CA Number	6736	An observation sheet was completed and the technician was made aware of the problem immediately.
Responded By	ТВ	
		CSM followed up with the customer via e-mail explaining that the CA experienced technical
Response Date	4/2/02	difficulties at the time of the call. The problem was corrected immediately.
Resolution	4/2/02	

## Technical Complaints-Line Disconnected

Inquire Date 1/14/02
Record ID 9077
Call Taken By DF

CA Number 1218
Responded By TB

Response Date 1/15/02

**Resolution** 1/15/02

TTY user connected with CA 1218F at approximately 9:40 a.m. today and was disconnected from the CA. TTY user gave the CA the number to dial. The CA dialed the number and connected with the voice user. The TTY user typed their first response to be voiced by the CA with a "GA," but it appeared the CA was no longer on the line. TTY caller noticed that there was a fast busy on their end. Person requested a follow-up call.

Customer Service Aide checked with the technician, processed the feedback form and gave it to the supervisor. CSA received response from the supervisor stating that the CA noticed that the TTY user stopped typing. CA asked if customer was still there and there was no response.

CA informed the voice party to hold and asked again if the TTY user was still there. Again, no response. CA alerted the supervisor and the supervisor informed the voice party that we were no longer receiving typing from the TTY user and disconnected the voice party.

CSM sent an e-mail to the TTY user explaining that the relay user's telephone line had disconnected.

### Technical Complaints-Line Disconnected

Relay user called to complain that CA 6592 disconnected him in the middle of call. Customer would like a follow-up.

Inquire Date 1/14/02
Record ID 9073
Call Taken By JB

CA Number 6592
Responded By JB

 Response Date
 1/14/02

 Resolution
 1/14/02

Customer Service Representative processed the feedback form and gave it to the supervisor. CSR received response from the supervisor stating that the caller was disconnected in the middle of call. However, the CA does not know why the call was disconnected.

CA was reminded to always document the activity at the workstation when this happens. Customer was contacted to follow up on the situation. Customer seemed satisfied.

## Technical Complaints--Line Disconnected

Inquire Date10/24/01Record ID8436Call Taken ByLS/TB

CA Number 6827Responded By LS

**Response Date** 10/24/01 **Resolution** 10/24/01

Customer called to inform us that after she typed a very long message, she did not get any typing from the CA. Customer asked if the CA was there and didn't receive a response. It seemed as if the CA disconnected.

Customer Service staff processed the feedback form and gave it to the supervisor. CS staff received a response from the supervisor stating that the CA experienced a technical problem. The CA did not hang up on the caller.

An observation sheet was completed and our technician was informed of the situation, which was corrected immediately. CS staff called the customer back and explained what happened.

### Technical Complaints--Line Disconnected

Customer called to complain that the CA disconnected her call. Customer said a follow-up is not necessary.

Inquire Date 9/7/01
Record ID 8060
Call Taken By
CA Number 1179
Responded By TB

 Response Date
 9/11/01

 Resolution
 9/11/01

Customer Service Interpreter processed the feedback form and gave it to the supervisor. CA explained that her keyboard locked up and the computer had to be restarted.

The CA called for a supervisor to assist. The supervisor restarted the computer but the call was disconnected. Technician was made aware of the situation and the problem was corrected immediately.

# Technical Complaints--Line Disconnected

Inquire Date 8/6/01
Record ID 7744
Call Taken By TB

CA Number 6792
Responded By TB

Response Date 8/6/01

8/6/01

Resolution

Customer called to report that when attempting to leave a message on the called party's voice answering machine, he got disconnected in the middle of call. Customer would like a follow-up via e-mail.

Customer Service Manager processed the feedback form and gave it to the supervisor. CSM received a response from the supervisor stating that the CA experienced a technical problem and the call was actually disconnected right after the caller typed the message out and gave the GA to the CA.

The CA could not dial back to the answering machine and leave the caller's message.

The CA completed an observation form. CSM sent an e-mail to the customer with the requested information.